Verify that the RJ45 cable is connected to the WAN plug on the back of the Pipeline unit.