



Icon

Initialization

Documentation

Mask type:

HILBERT. A paso baja.

Prompt

Type

Variable

Add

Frecuencia Portadora

edit

Fc

Delete

FFT size

edit

n_in

Up

Tiempo Muestreo Chip

edit

Tcs

Down

<<end of parameter list>>

Prompt:

Frecuencia Portadora

Control type:

Edit

Variable:

Fc

Assignment:

Evaluate

Popup strings:

Initialization commands:

```
N=n_in;  
f=[-3.175:(6.4/N):3.175];  
y=(1+sign(f));
```

OK

Cancel

Unmask

Help

Apply